









Kuweta do uprawy roślin

Czujnik wilgoci

145

215

105

Szalka wagi

Czujnik tensometryczny 0-5kg

D

C

B

A

D

C

B

A

6

5

4

3

2

1

6

5

4

3

2

1

6

5

4

3

2

1

6

5

4

3

2

1